

GLACIER PERFORATED

MR16 Hanging Down Light



DESCRIPTION

Based on our original Glacier Hanging Down Light, the Glacier Perforated Hanging Down Light offers a modern, elegant look. The precision machined perforations soften lighting, making it easy on the eyes while creating ambiance.

Part Number: **GLACIER-HDL-MR16-BR-PERF-BR-(NL)**
-BR-BLK-PERF-BR-BLK-(NL)
CU-PERF-CU-(NL)

GLACIER PERFORATED HANGING DOWN LIGHT

Use	Downlighting Techniques in Trees or Architecture by Hanging on a Chain or Cable
Includes	LightingShrink Professional Crimp and Heat Shrink Cable Connector Includes MR16, 4W, 2700K, 60° When Purchased with a Lamp
Lamp	MR16 or Chameleon MR16 for RGBW Applications
Finish	Brass, Copper, or Black Brass (Cerakote®)




Brass (BR)



Copper (CU)



Black Brass + Cerakote®
(BR-BLK)





GLACIER-HDL-MR16-BR-PERF-BR

INSTALLING THE FIXTURE

1. Unscrew the fixture body from the base.
2. Remove the stainless steel snap ring from the lamp holder.
3. Install the lamp in the socket.
4. Lay the front of the lamp inside the lamp holder and install the snap ring on the back side lip of the MR16 lamp.
5. Reinstall the lamp holder into the fixture body.

HANGING THE FIXTURE

- **IMPORTANT: DO NOT INSTALL ON OR NEAR ANY HIGH VOLTAGE POWER LINES**
1. Hang the fixture from a secure stainless steel eye bolt, with or without a chain.
 2. Create a drip loop with the wire by bending the wire to a slope one inch below the fixture cap.